

DPA ID	ELEMENT	FINDS	FOUND	IMAGE
4	Strong room	Ink well and stand	On table by the wall	
		Diary	On table by the wall	
		Ledgers	From different areas within the room	
7	Lift Machinery	Waiting for soil removal		
10	Mud Pit	The mud was solid - used a chisel for removal		
		Hoe - head	Mid layer of mud	
		Wooden stick - maybe the handle for the hoe	Mid layer of mud	

Metal water pipe? - end fitting similar to the pipes going into the vats

Bottom of mud pit



Glass Bottle - 2 pieces

Mid layer of mud



Electrical light fitting

Found sitting on 1st layer of mud



Ceramic light fitting

Found sitting on 1st layer of mud



Bakelite light fitting

Found sitting on 1st layer of mud



Towels

Found through out the layers of mud



Towel - Wording -N

Found sitting on 1st layer of mud



Towel - Wording -Health

Found sitting on 1st layer of mud



Metal head - maybe part of a stirrer?

Found sitting on 1st layer of mud



Tap handle

Mid layer of mud



Wooden bung

Mid layer of mud




Clothing label MB101/1A - Bib & Brace Overalls

Sitting under loose layer of mud with towels



Ceramic piece - plate



Hose nozzle

Bottom of mud pit



	Hose nozzle	Bottom of mud pit	
	Hose	Found sitting on 1st layer of mud	
12 Baths			
Daulton - Women's L/H	Towel - Wording - Waikato		
Daulton - Women's R/H	Pipe	In a outlet L/H side of bath	
Daulton- Men's L/H	Brush	Under bath	 
	Towel	Under bath by outlet	

String

Under bath



14 Ceiling battens

Aluminium wood plugs

Ceiling



15 Timber cupboard

Beehive match box

Behind cupboard



Park Drive Tobacco packaging

Behind cupboard



Newspaper

Behind cupboard



Tiles

Found under a layer of soil



example of tiles from the boxes

Milk Station 600ml glass bottle

Found with the tiles



59 Floor Drain - Women's floor

Button

In drain

