



Table of Contents

1.0 INTRODUCTION.....	1
2.0 PURPOSE.....	1
3.0 SCOPE.....	1
4.0 STATUTORY CONSIDERATIONS.....	5
4.1 Introduction	5
4.2 Relevant Planning Documents and Rules	5
4.2.1 Bay of Plenty Regional Council Regional Policy Statement	5
4.2.2 Regional Water and Land Plan	5
4.2.3 Regional Water and Land Plan Rule applicability	6
4.2.4 Rotorua District Plan	6
5.0 IDENTIFICATION OF STRATEGIC OBJECTIVES FOR STORMWATER MANAGEMENT.....	6
5.1 Asset Management Plan.....	6
5.2 Lake Okareka Stormwater Management Objective	7
6.0 DESCRIPTION OF CATCHMENT.....	7
6.1 Built Environment.....	7
6.1.1 Land use and development.....	7
6.1.2 Existing stormwater reticulation and treatment	9
6.1.3 Catchment discharge locations	9
6.2 Potential Sources of Stormwater Contamination	14
6.2.1 Catchment land use activities and their contamination generation potential	14
6.2.2 Wastewater	18
6.3 Regionally Significant Infrastructure	18
6.4 Topography	18
6.4.1 Lake Okareka Catchment	18
6.4.2 Lake Okareka Settlement Catchment	18
6.5 Geology and Soils.....	19
6.6 Groundwater	19
6.7 Water Quantity	19
6.7.1 Stormwater runoff calculations	19
6.7.2 Flooding	20
6.8 Water Quality	20



VOLUME 1: COMPREHENSIVE STORMWATER CONSENT APPLICATION

6.8.1	Introduction	20
6.8.2	Water quality guidelines	20
6.8.3	Stormwater quality	21
6.8.4	Discharges below catchments 06-08	23
6.8.5	Lake water quality	25
6.8.6	Summary.....	25
6.9	Sediment Quality	25
6.10	Description of the Receiving Environment within the Lake Okareka Settlement.....	26
6.10.1	Catchment streams assessment.....	26
6.10.2	Stream health assessment.....	30
6.10.2.1	Invertebrate communities	30
6.10.2.2	Fish fauna.....	30
6.10.3	Identification of degraded receiving environments	31
6.10.4	Summary.....	32
7.0	PREDICTED LAND USE DEVELOPMENT AND GROWTH IN IMPERVIOUS COVER	32
7.1	Existing Development.....	32
7.2	Future Development	33
8.0	ASSESSMENT OF EFFECTS ON THE ENVIRONMENT	33
8.1	Introduction.....	33
8.2	Water Quality.....	33
8.2.1	Lake water quality class	33
8.2.2	Contaminants and effects on aquatic organisms	35
8.2.3	Nutrients and lake catchment.....	35
8.3	Sediment Quality	36
8.4	Water Quantity.....	36
8.5	Freshwater Ecology	36
8.6	Public Health Issues	36
9.0	STATUTORY ASSESSMENT	37
9.1	Resource Management Act 1991	37
9.1.1	Overview	37
9.1.2	Part 2 considerations	37
9.1.3	Part 3, Section 15 considerations	39
9.1.4	Part 6, Sections 104 to 107 considerations.....	39



VOLUME 1: COMPREHENSIVE STORMWATER CONSENT APPLICATION

9.2	Operative and Proposed RPS Relevant Objectives and Policies	40
10.0	CONSULTATION.....	40
10.1	Consultation Undertaken and Outcomes	40
10.2	RLWP Relevant Objectives and Policies	41
11.0	SUMMARY OF STORMWATER MANAGEMENT ISSUES IDENTIFIED.....	47
11.1	Flooding and Stormwater Quantity	47
11.1.1	Flooding around The Wash area, particularly between Millar Road and Steep Street	47
11.1.2	Drainage around the Lake Okareka Hall and some reserves.....	47
11.1.3	Flooding due to lake level rise during times of heavy rainfall	47
11.2	Water Quality and Stream Health	47
11.2.1	Minor erosion in stream/drainage channels	47
11.2.2	Phosphorous in stormwater	47
11.2.3	Low ecological values in streams.....	47
12.0	STORMWATER MANAGEMENT OPTIONS	48
12.1	Structural and Non-structural Options and Proposed Management Solutions: Flooding and Stormwater Quantity	48
12.1.1	Structural options	48
12.1.2	Non-structural option.....	48
12.2	Structural and Non-structural Options and Proposed Management Solutions: Stormwater Quality, Stream Health and Erosion.....	48
12.2.1	Structural options	48
12.2.2	Non-structural options.....	49
13.0	CONCLUSION	49
14.0	REFERENCES.....	49

TABLES

Table 1: Land use in Lake Okareka catchment.....	7
Table 2: Stormwater discharge quality from discharge point 5 (DP5).	22
Table 3: Residential stormwater quality (median, range).	23
Table 4: Dry weather water quality in DP6-8.	24
Table 5: Total recoverable metals in the <500 µm sediment fraction from discharge points 2, 6 and 8.	26
Table 6: Invertebrate taxa recorded at sampling sites.....	30
Table 7: New Zealand Freshwater Fish Database (NZFFD) records for Lake Okareka and tributaries. Accessed 21 February 2011.....	31
Table 8: Commentary on effects of stormwater discharge from Lake Okareka Settlement on the Natural State (Lake) Water Quality Classification for Lake Okareka.	34



VOLUME 1: COMPREHENSIVE STORMWATER CONSENT APPLICATION

Table 9: Analysis of the effect of the stormwater discharge from the Lake Okareka Settlement compared to relevant objectives and policies in the Regional Land and Water Plan 41

FIGURES

Figure 1: Site location map.....	2
Figure 2: Network catchment boundaries.....	3
Figure 3: Location of outlets and stormwater features.	4
Figure 4: Land cover in the Lake Okareka catchment.....	8
Figure 5: DP1 discharge point on the edge of Lake Okareka.....	10
Figure 6: DP2 (The Wash) discharge point to Lake Okareka. The photo on the left shows the overland flow path to the lake whereas the photo on the right shows the outlet from the confined channel.....	11
Figure 7: DP4, the discharge point to Lake Okareka. The photo on the left shows the pipe outlet to a small open channel that spills to the lake as shown in the photo to the right.....	11
Figure 8: DP5, the discharge point to Lake Okareka. The photo on the left shows the wooden outfall to a small open channel that flows to the lake shown in the photo to the right.	12
Figure 9: DP6 and 7, the discharge point to Lake Okareka. The photo on the left shows the pipe outlet to an open channel/drain that flows to the lake. The drain is shown in the photo to the right looking from the lake edge.	13
Figure 10: DP8 discharge point on the edge of Lake Okareka.....	13
Figure 11: DP9 discharge point on the edge of Lake Okareka. The photo to the left shows the submerged pipe end and the photo on the right shows the submerged pipe leaving landfall.	14
Figure 12: Left – Turnaround point with a discharge to lake. Sediment on road margins drain to lake without treatment. Right – Gravel driveway next to catchpit with silt/gravel diversion bags around grate.	15
Figure 13: Lower reaches of The Wash.	16
Figure 14: Minor erosion around a private stormwater connection pipe flowing into The Wash and the rudimentary measures to control erosion.	17
Figure 15: Benn Road open drain and minor erosion of main channel.	17
Figure 16: Watercourses in Lake Okareka Settlement catchment.	27
Figure 17: Stream habitat conditions in the a) upper and b) mid-reaches of the Okareka Loop Road stream running parallel to Okareka Loop Road.	28
Figure 18: Instream habitat conditions observed in the a) lower section of Okareka Loop Road stream and b) Benn Road stream.	29
Figure 19: Instream habitat conditions observed in the a) upper reach and b) lower reach of The Wash sub-catchment.	29
Figure 20: Potential artificial barrier (culvert) to fish passage observed within Benn Road Stream.	31
Figure 21: Degraded receiving environments observed within Okareka Loop Road stream including a) excessive algae growth and b) silt deposition.	32

APPENDICES

APPENDIX A

Report Limitations



VOLUME 1: COMPREHENSIVE STORMWATER CONSENT APPLICATION

APPENDIX B

Lake Okareka Catchment Management Plan

APPENDIX C

Planning Documents

APPENDIX D

Lakes A Zone Map

APPENDIX E

Historical Lake Levels

APPENDIX F

Consultation

DRAFT